



Space Shuttle Main Engine

SSME 0523, 902-772 Incident Investigation



Damage to the HPFTP/AT

The majority of the damage occurred in the turbine-end. Damage incurred in the turbine downstream of the 1st blades resulted from impact. Pump-end hardware was damaged by rub and the loss of roller bearing support.




Turbine inlet struts and 1st vanes (stator) were eroded.

The airfoils of a segment of 1st vanes were eroded through, liberating that segment's inner platform to impact the 1st blades.



The 1st stage blades, and other downstream hardware, have been damaged from impact.




The roller bearing failed during the shut-down transient when it experienced loads $\approx 35 \times$ nominal.

Cronidur 30 inner race (the outer race was recovered intact)

6 of 14 Si_3N_4 rollers were recovered.

Armalon cage




Space Shuttle Main Engine

SSME 0523, 902-772 Incident Investigation




ENGINE 0523 FUEL SYSTEM CONTAMINATION POST 902-772



NOTE 1: Total amount of primary tape contamination estimated to be 24 square inches

NOTE 2: Other contamination consists of HPFTP/AT debris generated during the failure and insignificant amounts of various debris normally found during disassembly



Space Shuttle Main Engine

SSME 0523, 902-772 Incident Investigation




CANDIDATE POINTS OF ENTRY FOR ENGINE 0523 TAPE CONTAMINATION

LIKELIHOOD FOR POINTS OF ENTRY

● HIGH	Clear Path to Manifolds
● MEDIUM	No MCC/Noz Tape Debris
● LOW	No MCC/Nozzle Tape Debris after Engine Chill (NOTE 2)
● LOWER	No HPFP Tape Debris, & No MCC/Nozzle Tape Debris after Engine Chill (NOTE 2)
● LOWEST	No FFM Tape Debris, No FFM Detection, No HPFP Tape Debris, & No MCC/Nozzle Tape Debris after Engine Chill (NOTE 2)


PRIMARY PATH TO MANIFOLD
 SECONDARY PATH to Manifold

- CRITERIA**
1. Joint broken since last hot-fire
 2. Path from joint to pre-burner fuel manifold
 3. Joint diameter greater than 1 inch (Note 1)



NOTE 1: 24 square inches of tape forms a ball greater than 1" dia.

NOTE 2: Chilled tape is brittle and more likely to contaminate the MCC and Nozzle



Space Shuttle Main Engine SSME 0523, 902-772 Incident Investigation



Summary of Board Findings

- **Most probable failure scenario and Principle finding**
- **During the processing and assembly of SSME 0523, Permacel P-670 tape contamination was introduced into the fuel system.**
 - Despite normal inspections, the tape went unnoticed during the remainder of the assembly and pretest operations.
- **At engine start, the tape was forced downstream and came to rest as debris in the fuel manifold of the FPB, causing a localized high mixture ratio in the FPB.**
- **The resulting hot streak impinged on the turbine inlet housing struts and first stage vanes.**
- **A vane segment burned through and the inner section fell into the first stage blades.**
 - This caused rotor imbalance and significant turbine and pump damage.
- **Summary of Major Recommendations**
- **Verify that all systems are free of foreign object debris prior to hotfire.**
- **Limit the opportunity for contamination introduction by minimizing the use of potential contaminants and using permanent closures on joints where applicable.**
- **Keep joints closed at all times when access is not required to perform work.**
- **Implement an improved method of accountability for loose, non-serialized materials used in SSME processing.**
- **Also, investigate the use of reusable barriers when a contamination barrier is required.**